

Errata of

Embedded SoPC Design with Nios II Processor and Verilog Examples (Last Updated 08/01/2012)

• p.377, Figure 15.19: wrong image was embedded: the correct one should be



The "←" symbols of RT operations in the ASMD chart are missing in p.157, Figure 7.2(a), due to printer's font problem; the correct diagram should be



- (a) ASMD segment
- The "←" symbols of RT operations in the ASMD charts are also missing in the following figures:
 - o Figure 7.3(a) in p.159.
 - Figure 7.4 in p.160.
 - o Figure 7.6 in p.162.
 - o Figure 7.7 in p.167.
 - o Figure 7.8 in p.169.
 - o Figure 7.11 in p.179.
 - o Figure 17.2 in p.426.
 - o Figure 17.5 in p.431.

 - o Figure 21.1 in p.666.
 - Figure 22.4.1 in p.690.